

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 9/3/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S06AA_011MH

Test ID: D1032-020010

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S06AA_011MH
0			Water Level	
34.09999847			Dye Test Visible	FROM CLEANOUT AT 903
34.09999847			Dye Test Not Visible	FROM DOWN SPOUT AT 903
34.09999847			General Observation	DYE FROM DOWN SPOUT GOES TO CU
34.09999847			Abandoned Survey	DYE FLOOD COMPLETED